

Fig. 8




Fig. 1



6626260-19320160




Fig. 4a

BY	DRAFTSMAN	CLASS	SUBCLASS




Fig. 4b

66250" 432410

IP SOURCE ADDRESS	IP DESTINATION ADDRESS	COMPONENT TYPE	COMPONENT VERSION	COMPONENT HEALTH STATUS
COMPONENT #1 IP ADDRESS	VENDOR SITE #1	LIMIT SWITCH	VERSION 3.1	CONTACT DEGRADING
COMPONENT #2 IP ADDRESS	VENDOR SITE #1	VIBRATION SENSOR	VERSION 4.0	OUT OF CALIBRATION
.
COMPONENT N-1 IP ADDRESS	VENDOR SITE #2	MOTOR	VERSION 2.0	VIBRATION HIGH
COMPONENT N IP ADDRESS	VENDOR SITE #1	PUSH BUTTON	VERSION 1.1	GOOD

Fig. 5

IP SOURCE ADDRESS	COMPONENT LOCATION INFORMATION	COMPONENT TYPE	LATEST COMPONENT VERSION	COMPONENT HEALTH	COMPONENT ACTION
COMPONENT #1 IP ADDRESS	CUSTOMER, SITE #1 LOCATION A	LIMIT SWITCH	VERSION 3.1	CONTACT DEGRADING	NEEDS REPLACEMENT
COMPONENT #2 IP ADDRESS	CUSTOMER, SITE #1 LOCATION K	VIBRATION SENSOR	VERSION 4.0	CONTACT DEGRADING	NEEDS REPLACEMENT
.
COMPONENT N-1 IP ADDRESS	CUSTOMER #1, SITE #2 LOCATION D	MOTOR	VERSION 2.0	VIBRATION HIGH	NEEDS MAINTENANCE
COMPONENT N IP ADDRESS	CUSTOMER #2, SITE #1 LOCATION K	PUSH BUTTON	VERSION 2.1	GOOD	NEEDS UPGRADE TO VERSION 2.1

Fig. 6




Fig. 7




Fig. 8